

OPEL VIVARO 1.6 CDTI ecoFLEX L2H1



Itemno 307535
Kind Van
Specification Closed Van
Matriculation year 2015 / 10
Mileage 166,135 km

Chassisnumber
W0L2F7318GV603679

Technical condition

Remarks

lang, airco, navi, pdc, imperiaal, trekhaak,
(A15)



Price €8900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

| | |
|-------------------------------------|------------------------|
| Number of axles | 2 |
| Configuration | 4x2 |
| Loading Capacity | 1,299 kg |
| Own weight | 1,711 kg |
| Gross vehicle weight | 3,010 kg |
| Unbraked towing capacity | 750 kg |
| Braked towing capacity, center axle | 2,000 kg |
| Towing bracket | |
| Wheelbase | 350 cm |
| Suspension type | coil spring suspension |

Cabin

| | |
|--------------------|----------------|
| Cabin type | single cabin |
| Cruise control | |
| Airconditioning | |
| Number of airbags | 2 |
| Parking assistance | Front and back |
| Coloured windows | |
| Electric windows | |
| Electric mirrors | |
| Partition | |
| GPS navigation | |
| Color | Yellow |
| maintenance Guide | |
| Heated mirrors | |

Drivetrain

| | |
|-------------------|----------------|
| Engine capacity | 88 Kw (120 Hp) |
| Fuel type | diesel |
| Euro | 5 |
| Distribution type | Timing chain |
| Gearbox kind | Manual |
| Number of Gears | 6 |
| Power steering | |
| ABS | |
| ASR | |

Superstructure

| | |
|------------------|-------------|
| Inner box length | 262 cm |
| Inner box width | 159 cm |
| Inner box height | 137 cm |
| Load bed height | 56 cm |
| Roof-rack | with roll |
| Back doors | Double door |

Chairs

| | |
|-----------------|-------|
| Number of seats | 3 |
| Seat cover | cloth |

Remarks

| | |
|---------|--|
| Remarks | lang, airco, navi, pdc, imperiaal, trekhaak, side bars |
|---------|--|

Tyres/Wheels

Sparewheel

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 205/65R16,0
coil spring suspension
Disc brakes



Tire size: 205/65R16,0
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements