

MERCEDES-BENZ SPRINTER 513 CDI



Itemno 307668
Kind Van
Specification Frigo
Matriculation year 2016 / 03
Mileage 165,655 km

Chassisnumber
WDB9061551N659690

Technical condition 

Remarks
KOELWAGEN CARRIER AC AUTOMAAT
(A15)



Price € 23950

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Twin tires	✓
Loading Capacity	365 kg
Own weight	3,135 kg
Gross vehicle weight	3,500 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,000 kg
Wheelbase	433 cm
Suspension type	spring suspension

Cabin

Cabin type	single cabin
Cruise control	✓
Airconditioning	✓
Number of airbags	1
Parking assistance	None
Electric windows	✓
Electric mirrors	✓
Partition	✓
Color	Blue
Reversing camera	✓

Drivetrain

Engine capacity	95 Kw (129 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing chain
Gearbox kind	Automatic
Power steering	✓
ABS	✓
ASR	✓

Superstructure

Build kind	Extra long - Standard roof
Inner box length	450 cm
Inner box width	207 cm
Inner box height	205 cm
Load bed height	91 cm
Netto height	191 cm
Rear step	✓
Roof-rack	None
Sidedoors	1
Back doors	Double door

Chairs

Number of seats	3
Seat cover	cloth

Refrigeration unit

Enginemake frigo-unit	Carrier
Enginetype frigo-unit	Pulsor 600mt
Enginetype frigo-unit	electrical
Type of cooling	Cooling and freezing
Day/night cooling	day and night cooling

Remarks

Remarks	KOELWAGEN CARRIER AC AUTOMAAT EURO6!
---------	---

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Refrigeration unit

Systems

Tyres/Wheels

Tyres

Tires and axles



1

Tire size: 195/75R16,0
spring suspension
Disc brakes



2

Tire size: 195/75R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements