

MERCEDES-BENZ VITO 114 L3 XL Airco Trekhaak



Itemno 307761
Kind Van
Specification Closed Van
Matriculation year 2019 / 10
Mileage 92,140 km

Chassisnumber
WDF44760513664808

Technical condition

Remarks
L3 XL Airco Trekhaak Mf-Stuurwiel Cruise
(A15)

Price €23900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

| | |
|-------------------------------------|------------------------|
| Number of axles | 2 |
| Configuration | 4x2 |
| Loading Capacity | 1,034 kg |
| Own weight | 1,766 kg |
| Gross vehicle weight | 2,800 kg |
| Unbraked towing capacity | 750 kg |
| Braked towing capacity, center axle | 2,000 kg |
| Towing bracket | |
| Wheelbase | 343 cm |
| Suspension type | coil spring suspension |

Cabin

| | |
|--------------------|--------------|
| Cabin type | single cabin |
| Cruise control | |
| Airconditioning | |
| Number of airbags | 2 |
| Rear wiper | |
| Parking assistance | None |
| Coloured windows | |
| Electric windows | |
| Electric mirrors | |
| Partition | |
| Color | Gray |
| Heated mirrors | |

Drivetrain

| | |
|-------------------|-----------------|
| Engine capacity | 100 Kw (136 Hp) |
| Fuel type | diesel |
| Euro | 6 |
| Distribution type | Timing chain |
| Gearbox kind | Manual |
| Number of Gears | 6 |
| Power steering | |
| ABS | |
| ASR | |

Superstructure

| | |
|------------------|----------|
| Inner box length | 270 cm |
| Inner box width | 166 cm |
| Inner box height | 136 cm |
| Load bed height | 59 cm |
| Roof-rack | None |
| Back doors | taillift |

Chairs

| | |
|-----------------|-------|
| Number of seats | 2 |
| Seat cover | cloth |

Remarks

| | |
|---------|---|
| Remarks | L3 XL Airco Trekhaak Mf-Stuurwiel Cruise 136Pk Euro6! |
|---------|---|

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 195/65R16,0
coil spring suspension
Disc brakes



Tire size: 195/65R16,0
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements