

OPEL VIVARO 1.6 CDTI



Itemno 307880
Kind Van
Specification Closed Van
Matriculation year 2015 / 07
Mileage 285,284 km

Chassisnumber
W0L2F711FFV645201

Technical condition

Remarks
LANG DUBBELCABINE AC
(A15)

Price €9950

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	1,086 kg
Own weight	1,854 kg
Gross vehicle weight	2,940 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,000 kg
Towing bracket	
Wheelbase	350 cm
Suspension type	coil spring suspension

Cabin

Cabin type	double cabin
Cruise control	
Airconditioning	
Number of airbags	4
Parking assistance	Back
Electric windows	
Electric mirrors	
Partition	
GPS navigation	
Color	Blue
Reversing camera	

Drivetrain

Engine capacity	88 Kw (120 Hp)
Fuel type	diesel
Euro	5
Distribution type	Timing chain
Gearbox kind	Manual
Number of Gears	6
Power steering	
ABS	
ASR	

Superstructure

Build kind	Medium length - Standard roof
Inner box length	185 cm
Inner box width	164 cm
Inner box height	137 cm
Load bed height	55 cm
Netto height	130 cm
Roof-rack	None
Sidedoors	1
Side windows	2
Back doors	Double door

Chairs

Number of seats	5
Seat cover	cloth

Remarks

Remarks	LANG DUBBELCABINE AC
---------	----------------------

Tyres/Wheels

Sparewheel	
Spare tire profile	5 mm

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 205/65R16,0
coil spring suspension
Disc brakes



Tire size: 205/65R16,0
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements