# **RENAULT MASTER T35 2.3 DCI**



307882 Itemno Kind Van Specification Closed Van Matriculation year 2014 / 01 Mileage 170,277 km

Chassisnumber VF6MFFEFC49726789

Technical condition Remarks







Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01







**Price €10450** 

# **Equipment**

#### Chassis

Number of axles Configuration 4x2 Loading Capacity 1,498 kg Own weight 2,002 kg 3,500 kg Gross vehicle weight Unbraked towing capacity 750 kg Braked towing capacity, center 2,500 kg

Towing bracket

Wheelbase 368 cm

Suspension type spring suspension

# Cabin

Cabin type single cabin

Cruise control

Airconditioning

Number of airbags Parking assistance None

Electric windows Electric mirrors

Partition

**GPS** navigation

Color white

## **Drivetrain**

110 Kw (149 Hp) Engine capacity

Fuel type diesel Euro

Distribution type Timing chain Gearbox kind Manual Number of Gears 6

ABS **ASR** 

# Superstructure

Build kind Medium length - High roof Inner box length 305 cm 175 cm Inner box width 188 cm Inner box heigth Load bed heigth 58 cm 180 cm Netto height Roof-rack None Sidedoors

Back doors Double door

#### Chairs

Number of seats 3 Seat cover cloth

# Remarks

Remarks **AIRCO** 

# Tyres/Wheels

Sparewheel

Spare tire profile 5 mm

#### **Contact information**



info@kleyn.com Tel: +31 183 668 444

#### Certified and professional












Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

# **Dimensions**



# VANS

LEYN KLEYN KI

TRAILERS



Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

# **Inspection report**

# Chassis

Dashboard display codes

Electrical

# Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

### **Drivetrain**

Engine, general 33330 Cooling system 00000 Fuel system 0000 Exhaust system 0000 Greasing system Gearbox 0000 Clutch 00000 Drivetrain 33330

#### Superstructure

Internal condition

External condition

# Tyres/Wheels

Tyres

# **Tires and axles**



Tire size: 225/65R16,0 coil spring suspension Disc brakes



Tire size: 225/65R16,0 spring suspension Disc brakes

# Contact information



info@kleyn.com Tel: +31 183 668 444

#### Legenda for inspection report

Very good state
Good state
Reasonable state

Moderate state

Does not meet requirements