

## MERCEDES-BENZ SPRINTER 514



Itemno 307956  
Kind Van  
Specification Closed box  
Matriculation year 2020 / 10  
Mileage 89,685 km

**Chassisnumber**  
W1V9071551N083897

Technical condition

**Remarks**

( A15 )

**Price €33900**

# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

## Equipment

### Chassis

Number of axles 2  
Configuration 4x2  
Loading Capacity 540 kg  
Own weight 2,960 kg  
Gross vehicle weight 3,500 kg  
Unbraked towing capacity 750 kg  
Braked towing capacity, center axle 2,000 kg  
Wheelbase 433 cm  
Suspension type spring suspension

### Cabin

Cabin type single cabin  
Cruise control  
Airconditioning  
Number of airbags 1  
Parking assistance None  
Coloured windows  
Electric windows  
Electric mirrors  
Color white  
Heated mirrors

### Drivetrain

Engine capacity 105 Kw (143 Hp)  
Fuel type diesel  
Euro 6  
Distribution type Timing chain  
Gearbox kind Automatic  
Power steering  
ABS  
ASR

### Superstructure

Inner box length 429 cm  
Inner box width 211 cm  
Inner box height 220 cm  
Load bed height 91 cm  
Roof-rack None  
Back doors taillift

### Chairs

Number of seats 3  
Seat cover cloth

### Taillift

Taillift  
Tail-lift kind normal  
Tail-lift capacity 750 kg  
Tail-lift make DHOLANDIA  
Tail-lift size 210x145

### Contact information



info@kleyn.com


Tel: +31 183 668 444

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

## Inspection report

### Chassis

Dashboard display codes

Electrical

### Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

### Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

### Superstructure

Internal condition

External condition

### Taillift

Controls

System

### Tyres/Wheels

Tyres



1  
Tire size: 195/75R16,0  
spring suspension  
Disc brakes



2  
Tire size: 195/75R16,0  
spring suspension  
Disc brakes

## Contact information



info@kleyn.com

Tel: +31 183 668 444

## Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements