

## FORD TRANSIT 350 2.2 TDCI



Itemno 308014  
Kind Van  
Specification Frigo  
Matriculation year 2015 / 01  
Mileage 121,107 km

**Chassisnumber**  
WF0XXXTTGXEG49198

Technical condition

**Remarks**  
KOELWAGEN DAG/NACHT AIRCO  
( A15 )

**Price €15950**

# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®  
P.O. Box 3  
4214 ZJ Vuren  
Zeiving 12  
4214 KT Vuren  
The Netherlands

IBAN: NL32RABO0317847430  
SWIFT/BIC: RABONL2U

KvK 11044363  
BTW/VAT NL807901337B01

## Equipment

### Chassis

Number of axles 2  
Configuration 4x2  
Loading Capacity 1,329 kg  
Own weight 2,171 kg  
Gross vehicle weight 3,500 kg  
Unbraked towing capacity 750 kg  
Braked towing capacity, center axle 2,800 kg  
Wheelbase 375 cm  
Suspension type spring suspension

### Cabin

Cabin type single cabin  
Cruise control  
Airconditioning  
Number of airbags 1  
Parking assistance Front and back  
Coloured windows  
Electric windows  
Electric mirrors  
Partition  
Color white  
Heated mirrors

### Drivetrain

Engine capacity 92 Kw (125 Hp)  
Fuel type diesel  
Euro 5  
Distribution type Timing belt  
Gearbox kind Manual  
Number of Gears 6  
Power steering  
ABS  
ASR

### Superstructure

Build kind Extra Long - High roof  
Inner box length 320 cm  
Inner box width 175 cm  
Inner box height 215 cm  
Load bed height 65 cm  
Rear step  
Roof-rack None  
Back doors Double door

### Chairs

Number of seats 3  
Seat cover cloth

### Refrigeration unit

Enginetype frigo-unit Waeco frigo  
Enginetype frigo-unit electrical  
Type of cooling Cooling  
Day/night cooling day and night cooling

### Remarks

Remarks KOELWAGEN DAG/NACHT  
AIRCO

### Tyres/Wheels

Sparewheel

### Contact information




info@kleyn.com  
Tel: +31 183 668 444

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®  
P.O. Box 3  
4214 ZJ Vuren  
Zeiving 12  
4214 KT Vuren  
The Netherlands

IBAN: NL32RABO0317847430  
SWIFT/BIC: RABONL2U

KvK 11044363  
BTW/VAT NL807901337B01

## Inspection report

### Chassis

Dashboard display codes

Electrical

### Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

### Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

### Superstructure

Internal condition

External condition

### Refrigeration unit

Systems

### Tyres/Wheels

Tyres

## Tires and axles



1  
Tire size: 235/65R16,0  
coil spring suspension  
Disc brakes



2  
Tire size: 235/65R16,0  
spring suspension  
Disc brakes

### Contact information



info@kleyn.com  
Tel: +31 183 668 444

### Legenda for inspection report

Very good state  
 Good state  
 Reasonable state  
 Moderate state  
 Does not meet requirements