

## CITROEN JUMPER 2.0 BLUEHDI L2H2



Itemno 308192  
Kind Van  
Specification Closed Van  
Matriculation year 2018 / 10  
Mileage 277,483 km

**Chassisnumber**  
VF7YB1MFB12J46996

Technical condition

**Remarks**  
L2H2, airco, navi, pdc  
( A15 )

**Price €10750**

# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®  
P.O. Box 3  
4214 ZJ Vuren  
Zeiving 12  
4214 KT Vuren  
The Netherlands

IBAN: NL32RABO0317847430  
SWIFT/BIC: RABONL2U

KvK 11044363  
BTW/VAT NL807901337B01

## Equipment

### Chassis

Number of axles 2  
Configuration 4x2  
Own weight 1,985 kg  
Gross vehicle weight 3,300 kg  
Wheelbase 345 cm  
Suspension type spring suspension

### Cabin

Cabin type single cabin  
Cruise control  
Airconditioning  
Number of airbags 2  
Parking assistance Back  
Electric windows  
Electric mirrors  
Partition  
GPS navigation  
Color white  
maintenance Guide  
Heated mirrors

### Drivetrain

Engine capacity 81 Kw (110 Hp)  
Fuel type diesel  
Distribution type Timing belt  
Gearbox kind Manual  
Number of Gears 6  
Power steering  
ABS  
ASR

### Superstructure

Inner box length 294 cm  
Inner box width 185 cm  
Inner box height 198 cm  
Load bed height 50 cm  
Netto height 178 cm  
Roof-rack None  
Back doors Double door

### Chairs

Number of seats 3  
Seat cover cloth

### Remarks

Remarks L2H2, airco, navi, pdc

### Tyres/Wheels

Sparewheel  
Spare tire profile 9 mm

### Contact information




info@kleyn.com  
Tel: +31 183 668 444

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN VANS

KLEYN GROUP KLEYN TRUCKS KLEYN TRAILERS KLEYN SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

## Inspection report

### Chassis

Dashboard display codes

Electrical

### Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

### Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

### Superstructure

Internal condition

External condition

### Tyres/Wheels

Tyres

## Tires and axles



1

Tire size: 215/70R15,0  
coil spring suspension  
Disc brakes



2

Tire size: 215/70R15,0  
spring suspension  
Disc brakes

## Contact information



info@kleyn.com

Tel: +31 183 668 444

## Legenda for inspection report

Very good state  
 Good state  
 Reasonable state  
 Moderate state  
 Does not meet requirements