

MERCEDES-BENZ SPRINTER 513 CDI



Itemno 308217
Kind Van
Specification Closed Van
Matriculation year 2009 / 07
Mileage 218,213 km

Chassisnumber
WDB9061551N421683

Technical condition

Remarks
LAADKLEP EN BAK XL AIRCO EURO5!
(A15)

Price € 14950

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Twin tires	✓
Loading Capacity	390 kg
Own weight	3,110 kg
Gross vehicle weight	3,500 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,000 kg
Wheelbase	433 cm
Suspension type	spring suspension

Cabin

Cabin type	single cabin
Airconditioning	✓
Number of airbags	1
Parking assistance	None
Electric windows	✓
Electric mirrors	✓
Color	Black
Reversing camera	✓

Drivetrain

Engine capacity	95 Kw (129 Hp)
Fuel type	diesel
Euro	5
Distribution type	Timing chain
Gearbox kind	Manual
Number of Gears	6
Power steering	✓
ABS	✓
ASR	✓

Superstructure

Inner box length	427 cm
Inner box width	211 cm
Inner box height	233 cm
Load bed height	100 cm
Netto height	228 cm
Roof-rack	None
Sidedoors	1
Back doors	taillift

Chairs

Number of seats	3
Seat cover	cloth

Taillift

Taillift	✓
Tail-lift kind	normal
Tail-lift capacity	750 kg
Tail-lift make	Dhollandia
Tail-lift size	260x215

Remarks

Remarks	LAADKLEP EN BAK XL AIRCO EURO5!
---------	---------------------------------

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes



Electrical



Cabin

Internal



External



Steering column



Suspension



Chassis



Brakes



Drivetrain

Engine, general



Cooling system



Fuel system



Exhaust system



Greasing system



Gearbox



Clutch



Drivetrain



Superstructure

Internal condition



External condition



Taillift

Controls



System



Tyres/Wheels

Tyres



1



Tire size: 195/75R16,0
spring suspension
Disc brakes

2



Tire size: 195/75R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements