

FIAT DUCATO 35 2.3



Itemno 308224
Kind Van
Specification Closed Van
Matriculation year 2017 / 08
Mileage 228,998 km

Chassisnumber
ZFA25000002F13199

Technical condition 

Remarks
XXL 180 PK AIRCO EURO6!
(A15)

Price € 15950

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Own weight	2,285 kg
Gross vehicle weight	3,500 kg
Wheelbase	404 cm
Suspension type	spring suspension

Cabin

Cabin type	single cabin
Cruise control	✓
Airconditioning	✓
Number of airbags	1
Parking assistance	None
Electric windows	✓
Electric mirrors	✓
Partition	✓
GPS navigation	✓
Color	white
Reversing camera	✓

Drivetrain

Engine capacity	130 Kw (177 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing belt
Gearbox kind	Manual
Number of Gears	6
Power steering	✓
ABS	✓
ASR	✓

Superstructure

Build kind	Extra Long - High roof
Inner box length	395 cm
Inner box width	186 cm
Inner box height	214 cm
Load bed height	56 cm
Netto height	176 cm
Roof-rack	None
Sidedoors	1
Back doors	Double door

Chairs

Number of seats	2
Seat cover	cloth

Remarks

Remarks	XXL 180 PK AIRCO EURO6!
---------	-------------------------

Tyres/Wheels

Sparewheel	✓
Spare tire profile	6 mm

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



1

Tire size: 225/75R16,0
spring suspension
Disc brakes



2

Tire size: 225/75R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements