

VOLKSWAGEN CRAFTER 2.0 TDI



Itemno 308226
Kind Van
Specification Closed Van
Matriculation year 2019 / 01
Mileage 135,327 km

Chassisnumber
WV1ZZSYZK9008740

Technical condition 

Remarks

AC EURO6

(A15)



Price €16950

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	1,020 kg
Own weight	1,980 kg
Gross vehicle weight	3,000 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,500 kg
Wheelbase	364 cm
Suspension type	spring suspension

Cabin

Cabin type	single cabin
Cruise control	
Airconditioning	
Number of airbags	1
Parking assistance	None
Electric windows	
Electric mirrors	
Partition	
Color	Blue
Reversing camera	

Drivetrain

Engine capacity	75 Kw (102 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing belt
Gearbox kind	Manual
Number of Gears	6
Power steering	
ABS	
ASR	

Superstructure

Build kind	Medium length - High roof
Inner box length	320 cm
Inner box width	178 cm
Inner box height	193 cm
Load bed height	58 cm
Netto height	183 cm
Roof-rack	None
Sidedoors	1
Back doors	Double door

Chairs

Number of seats	3
Seat cover	cloth

Remarks

Remarks	AC EURO6
---------	----------

Contact information



info@kleyn.com


Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP KLEYN TRUCKS KLEYN TRAILERS KLEYN SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



1

Tire size: 205/75R16,0
coil spring suspension
Disc brakes



2

Tire size: 205/75R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements