

OPEL VIVARO 1.6 L1H1 Airco Navi Eur6



Itemno 308262
Kind Van
Specification Closed Van
Matriculation year 2019 / 02
Mileage 101,897 km

Chassisnumber
W0VF7D604KV626540

Technical condition 

Remarks
L1H1 Airco Navi Camera Trekhaak 3-Zits
(A15)



Price €14900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	1,262 kg
Own weight	1,718 kg
Gross vehicle weight	2,980 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,000 kg
Towing bracket	
Wheelbase	310 cm
Suspension type	coil spring suspension

Cabin

Cabin type	single cabin
Cruise control	
Airconditioning	
Number of airbags	2
Parking assistance	Front and back
Electric windows	
Electric mirrors	
Partition	
GPS navigation	
Color	white
maintenance Guide	
Reversing camera	

Drivetrain

Engine capacity	92 Kw (125 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing chain
Gearbox kind	Manual
Number of Gears	6
Power steering	
ABS	
ASR	

Superstructure

Inner box length	230 cm
Inner box width	164 cm
Inner box height	134 cm
Load bed height	57 cm
Netto height	130 cm
Rear step	
Roof-rack	None
Sidedoors	1
Back doors	Double door

Chairs

Number of seats	3
Seat cover	cloth

Remarks

Remarks	L1H1 Airco Navi Camera Trekhaak 3-Zits 125Pk Oh-Historie Euro6!
---------	---

Tyres/Wheels

Sparewheel	
Spare tire profile	7 mm

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430


SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes 


Electrical 

Cabin

Internal 

External 

Steering column 

Suspension 

Chassis 

Brakes 

Drivetrain

Engine, general 

Cooling system 


Fuel system 

Exhaust system 

Greasing system 

Gearbox 

Clutch 

Drivetrain 

Superstructure

Internal condition 

External condition 

Tyres/Wheels

Tyres 

Tires and axles



1

Tire size: 205/65R16,0
coil spring suspension
Disc brakes



2

Tire size: 205/65R16,0
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

-  Very good state
-  Good state
-  Reasonable state
-  Moderate state
-  Does not meet requirements