

MERCEDES-BENZ SPRINTER 314 Koelwagen Laadk



Itemno 308267
Kind Van
Specification Frigo
Matriculation year 2017 / 03
Mileage 121,386 km

Chassisnumber
WDB9061331N702168

Technical condition

Remarks
Koelbakwagen Laadklep Dag/ Nacht Carrier
(A15)

Price € 33900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Loading Capacity 929 kg
Own weight 2,571 kg
Gross vehicle weight 3,500 kg
Unbraked towing capacity 750 kg
Braked towing capacity, center axle 2,000 kg
Wheelbase 367 cm
Suspension type spring suspension

Cabin

Cabin type single cabin
Airconditioning ✓
Number of airbags 1
Parking assistance None
Electric windows ✓
Color white

Drivetrain

Engine capacity 105 Kw (143 Hp)
Fuel type diesel
Euro 6
Distribution type Timing chain
Gearbox kind Manual
Number of Gears 6
Power steering ✓
ABS ✓
ASR ✓

Superstructure

Inner box length 355 cm
Inner box width 210 cm
Inner box height 210 cm
Load bed height 84 cm
Netto height 210 cm
Rear step ✓
Roof-rack None
Back doors Double door

Chairs

Number of seats 3
Seat cover cloth

Refrigeration unit

Enginemake frigo-unit Carrier
Enginetype frigo-unit xarios 300
Enginetype frigo-unit Compressor / electrical
Type of cooling Cooling and freezing
Day/night cooling day and night cooling

Taillift

Taillift ✓
Tail-lift kind normal
Tail-lift capacity 750 kg
Tail-lift make DHOLANDIA
Tail-lift size 215 x 160

Remarks

Remarks Koelbakwagen Laadklep Dag/
Nacht Carrier 143Pk Euro6!

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes



Electrical



Cabin

Internal



External



Steering column



Suspension



Chassis



Brakes



Drivetrain

Engine, general



Cooling system



Fuel system



Exhaust system



Greasing system



Gearbox



Clutch



Drivetrain



Superstructure

Superstructure



Internal condition



External condition



Refrigeration unit

Systems



Taillift

Controls



System



Tyres/Wheels

Tyres



Tires and axles



1

Tire size: 235/65R16,0
spring suspension
Disc brakes



2

Tire size: 235/65R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 444

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements