

## PEUGEOT PARTNER



Itemno 308282  
Kind Van  
Specification Closed Van  
Matriculation year 2013 / 06  
Mileage 415,587 km

**Chassisnumber**  
VF37B9HF0CN546787

Technical condition

**Remarks**

( A15 )

**Price €3450**

# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®  
P.O. Box 3  
4214 ZJ Vuren  
Zeiving 12  
4214 KT Vuren  
The Netherlands

IBAN: NL32RABO0317847430  
SWIFT/BIC: RABONL2U

KvK 11044363  
BTW/VAT NL807901337B01

## Equipment

### Chassis

Number of axles 2  
Configuration 4x2  
Loading Capacity 500 kg  
Own weight 1,360 kg  
Gross vehicle weight 1,860 kg  
Unbraked towing capacity 695 kg  
Braked towing capacity, center axle 1,160 kg  
Wheelbase 273 cm  
Suspension type coil spring suspension

### Cabin

Cabin type single cabin  
Airconditioning  
Number of airbags 1  
Parking assistance None  
Electric windows  
Electric mirrors  
Partition  
Color white  
Heated mirrors

### Drivetrain

Engine capacity 66 Kw (90 Hp)  
Fuel type diesel  
Euro 5  
Distribution type Timing chain  
Gearbox kind Manual  
Number of Gears 5  
Power steering  
ABS

### Superstructure

Inner box length 153 cm  
Inner box width 129 cm  
Inner box height 126 cm  
Load bed height 54 cm  
Netto height 115 cm  
Roof-rack None  
Back doors Double door

### Chairs

Number of seats 3  
Seat cover cloth

### Tyres/Wheels

Sparewheel

### Contact information




info@kleyn.com  
Tel: +31 183 668 444

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

## Inspection report

### Chassis

Dashboard display codes

Electrical

### Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

### Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

### Superstructure

Internal condition

External condition

### Tyres/Wheels

Tyres

## Tires and axles



1

Tire size: 195/65R15,0  
coil spring suspension  
Disc brakes



2

Tire size: 195/65R15,0  
coil spring suspension  
Disc brakes

## Contact information



info@kleyn.com

Tel: +31 183 668 444

## Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements