
PEUGEOT EXPERT



Itemno Kind Specification Matriculation year Mileage Chassisnumber VF3XUAHZ8DZ031515

308283 Van Closed Van 2013/08 345,491 km



P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles Configuration Loading Capacity Own weight Gross vehicle weight Unbraked towing capacity Braked towing capacity, center axle Towing bracket Wheelbase Aluminium rims Suspension type

Cabin

Cabin type Cruise control Airconditioning Number of airbags Parking assistance Coloured windows Electric windows Electric mirrors Partition **GPS** navigation Color Heated mirrors

Drivetrain

Engine capacity Fuel type Euro Distribution type Gearbox kind Number of Gears Power steering ABS ASR

2 4x2 1,185 kg 1,747 kg 2,932 kg 750 kg 2,000 kg

312 cm

coil spring suspension

single cabin

1 Back

white

94 Kw (128 Hp) diesel 5 Timing belt Manual 6

Superstructure

Inner box length Inner box width Inner box heigth Load bed heigth Roof-rack Back doors

Chairs

Number of seats Seat cover

Tyres/Wheels

Sparewheel

242 cm 159 cm 137 cm 60 cm None Double door

2 cloth

Certified and professional




Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Contact information



info@kleyn.com Tel: +31 183 668 444

Dimensions



Inspection report

Chassis	
Dashboard display codes	000
Electrical	
Cabin	
Internal	
External	
Steering column	
Suspension	
Chassis	
Brakes	
Drivetrain	
Engine, general	
Cooling system	
Fuel system	
Exhaust system	
Greasing system	
Gearbox	
Clutch	
Drivetrain	
Superstructure	
Internal condition	
External condition	
Tyres/Wheels	

Tyres

Contact information



info@kleyn.com Tel: +31 183 668 444

VANS KLEYN KLEYN KLEYN GROUD KLEYN KLEYN TRUCKS KLEYN SERVIC

Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Tires and axles



Legenda for inspection report Very good state Good state Reasonable state Moderate state Does not meet requirements