

## IVECO DAILY 35 C 140 FRIGO



Itemno 308375  
 Kind Van  
 Specification Frigo  
 Matriculation year 2019 / 09  
 Mileage 135,655 km

**Chassisnumber**  
 ZCFCD35A00D625178

Technical condition

**Remarks**  
 koelwagen, BI-TEMP, D/N, vriezer, airco,  
 ( A15 )

**Price €28900**

# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®  
 P.O. Box 3  
 4214 ZJ Vuren  
 Zeiving 12  
 4214 KT Vuren  
 The Netherlands

IBAN: NL32RABO0317847430  
 SWIFT/BIC: RABONL2U

KvK 11044363  
 BTW/VAT NL807901337B01

## Equipment

### Chassis

Number of axles 2  
 Configuration 4x2  
 Twin tires  
 Loading Capacity 485 kg  
 Own weight 3,015 kg  
 Gross vehicle weight 3,500 kg  
 Unbraked towing capacity 750 kg  
 Braked towing capacity, center axle 3,500 kg  
 Wheelbase 375 cm  
 Suspension type spring suspension

### Cabin

Cabin type single cabin  
 Cruise control  
 Airconditioning  
 Number of airbags 1  
 Parking assistance None  
 Electric windows  
 Electric mirrors  
 Color white  
 Heated mirrors

### Drivetrain

Engine capacity 100 Kw (136 Hp)  
 Fuel type diesel  
 Euro 6  
 Distribution type Timing belt  
 Gearbox kind Manual  
 Number of Gears 6  
 Power steering

### Superstructure

Inner box length 369 cm  
 Inner box width 191 cm  
 Inner box height 195 cm  
 Load bed height 95 cm  
 Netto height 194 cm  
 Rear step  
 Roof-rack None  
 Back doors Double door

### Chairs

Number of seats 3  
 Seat cover cloth  
 Comfort seat left

### Refrigeration unit

Enginemake frigo-unit Thermoking  
 Enginetype frigo-unit v 500 max  
 Enginetype frigo-unit Compressor / electrical  
 Type of cooling Cooling and freezing  
 Day/night cooling day and night cooling

### Remarks

Remarks koelwagen, BI-TEMP, D/N,  
 vriezer, airco, 135 dkm.

### Tyres/Wheels

Sparewheel  
 Spare tire profile 9 mm

### Contact information




info@kleyn.com  
 Tel: +31 183 668 444

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN VANS

**KLEYN** GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®  
P.O. Box 3  
4214 ZJ Vuren  
Zeiving 12  
4214 KT Vuren  
The Netherlands

IBAN: NL32RABO0317847430  
SWIFT/BIC: RABONL2U

KvK 11044363  
BTW/VAT NL807901337B01

## Inspection report

### Chassis

Dashboard display codes

Electrical

### Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

### Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

### Superstructure

Internal condition

External condition

### Refrigeration unit

Systems

### Tyres/Wheels

Tyres

## Tires and axles



Tire size: 195/75R16,0  
spring suspension  
Disc brakes



Tire size: 195/75R16,0  
spring suspension  
Disc brakes

### Contact information



info@kleyn.com  
Tel: +31 183 668 444

### Legenda for inspection report

Very good state  
 Good state  
 Reasonable state  
 Moderate state  
 Does not meet requirements