

IVECO DAILY 35 C 140 FRIGO



Itemno 308377
Kind Van
Specification Frigo
Matriculation year 2019 / 03
Mileage 133,833 km

Chassisnumber
ZCFC35A50D594560

Technical condition

Remarks
koelwagen, BI-TEMP, D/N, vriezer, airco,
(A15)

Price €28900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Twin tires	
Loading Capacity	485 kg
Own weight	3,015 kg
Gross vehicle weight	3,500 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	3,500 kg
Wheelbase	375 cm
Suspension type	spring suspension

Cabin

Cabin type	single cabin
Cruise control	
Airconditioning	
Number of airbags	1
Parking assistance	None
Electric windows	
Electric mirrors	
Color	white
Heated mirrors	

Drivetrain

Engine capacity	100 Kw (136 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing belt
Gearbox kind	Manual
Number of Gears	6
Power steering	
ABS	
ASR	

Superstructure

Inner box length	370 cm
Inner box width	191 cm
Inner box height	195 cm
Load bed height	96 cm
Netto height	195 cm
Rear step	
Roof-rack	None
Back doors	Double door

Chairs

Number of seats	3
Seat cover	cloth
Comfort seat	left

Refrigeration unit

Enginemaker frigo-unit	Thermoking
Enginetype frigo-unit	v500max
Enginetype frigo-unit	Compressor / electrical
Type of cooling	Cooling and freezing
Day/night cooling	day and night cooling

Remarks

Remarks	koelwagen, BI-TEMP, D/N, vriezer, airco, 133 dkm.
---------	---

Tyres/Wheels

Sparewheel	
Spare tire profile	5 mm

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes



Electrical



Cabin

Internal



External



Steering column



Suspension



Chassis



Brakes



Drivetrain

Engine, general



Cooling system



Fuel system



Exhaust system



Greasing system



Gearbox



Clutch



Drivetrain



Superstructure

Superstructure



Internal condition



External condition



Refrigeration unit

Systems



Tyres/Wheels

Tyres



1



Tire size: 195/75R16,0
spring suspension
Disc brakes

2



Tire size: 195/75R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements