

IVECO DAILY 35 C 140 FRIGO



Itemno 308378
Kind Van
Specification Frigo
Matriculation year 2018 / 11
Mileage 136,824 km

Chassisnumber
ZCFC35A70D591160

Technical condition

Remarks
koelwagen, BI-TEMP, D/N, vriezer, airco,
(A15)

Price €26900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Twin tires
Loading Capacity 485 kg
Own weight 3,015 kg
Gross vehicle weight 3,500 kg
Unbraked towing capacity 750 kg
Braked towing capacity, center axle 3,500 kg
Wheelbase 375 cm
Suspension type spring suspension

Cabin

Cabin type single cabin
Cruise control
Airconditioning
Number of airbags 1
Parking assistance None
Electric windows
Electric mirrors
Color white
Heated mirrors

Drivetrain

Engine capacity 100 Kw (136 Hp)
Fuel type diesel
Euro 6
Distribution type Timing belt
Gearbox kind Manual
Number of Gears 6
Power steering
ABS
ASR

Superstructure

Inner box length 369 cm
Inner box width 191 cm
Inner box height 195 cm
Load bed height 97 cm
Netto height 184 cm
Rear step
Roof-rack None
Back doors Double door

Chairs

Number of seats 3
Seat cover cloth

Refrigeration unit

Enginmake frigo-unit Thermoking
Enginetype frigo-unit v500 max
Enginetype frigo-unit Compressor / electrical
Type of cooling Cooling and freezing
Day/night cooling day and night cooling

Remarks

Remarks koelwagen, BI-TEMP, D/N, vriezer, airco, 136 dkm.

Tyres/Wheels

Sparewheel
Spare tire profile 8 mm

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes



Electrical



Cabin

Internal



External



Steering column



Suspension



Chassis



Brakes



Drivetrain

Engine, general



Cooling system



Fuel system



Exhaust system



Greasing system



Gearbox



Clutch



Drivetrain



Superstructure

Superstructure



Internal condition



External condition



Refrigeration unit

Systems



Tyres/Wheels

Tyres



Tires and axles



1
Tire size: 195/75R16,0
spring suspension
Disc brakes



2
Tire size: 195/75R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

