## **IVECO DAILY 35 C 140 FRIGO**



Itemno Kind Specification Matriculation year Mileage Chassisnumber

308379 Van Frigo 2019/10 116,538 km

ZCFCD35A90D625180



Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

# Equipment

### Chassis

Number of axles Configuration Twin tires Loading Capacity Own weight Gross vehicle weight Wheelbase Suspension type

### Cabin

Cabin type Cruise control Airconditioning Number of airbags Parking assistance Electric windows Electric mirrors Color Heated mirrors

### Drivetrain

Engine capacity Fuel type Euro Distribution type Gearbox kind Number of Gears Power steering ABS ASR

2 4x2

> 515 kg 2,985 kg 3,500 kg 375 cm spring suspension

single cabin

1 None

white

100 Kw (136 Hp) diesel 6 Timing belt Manual 6

## Superstructure

Inner box length Inner box width Inner box heigth Load bed heigth Netto height Rear step Roof-rack Back doors

## Chairs

Number of seats Seat cover Comfort seat

## **Refrigiration unit**

Enginemake frigo-unit Enginetype frigo-unit Enginetype frigo-unit Type of cooling Day/night cooling

#### Remarks Remarks

### Tyres/Wheels Sparewheel

Spare tire profile

369 cm 191 cm 195 cm 97 cm 180 cm

None Double door

3 cloth left

Thermoking v 500 max Compressor / electrical Cooling and freezing day and night cooling

koelwagen, BI-TEMP, D/N, vriezer, airco, 116 dkm.

8 mm

#### **Contact information**




info@kleyn.com Tel: +31 183 668 444

#### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## **Dimensions**



Tyres/Wheels

Tyres

# **Inspection report**

Chassis	
Dashboard display codes	
Electrical	
Cabin	
Internal	
External	
Steering column	
Suspension	
Chassis	
Brakes	
Drivetrain	
Engine, general	
Cooling system	
Fuel system	
Exhaust system	
Greasing system	
Gearbox	
Clutch	
Drivetrain	
Superstructure	
Superstructure	
Internal condition	
External condition	
Refrigiration unit	
Systems	99900

### **Contact information**



info@kleyn.com Tel: +31 183 668 444




Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

## **Tires and axles**



Legenda for inspection report	
	Very good state
	Good state
00000	Reasonable state
00000	Moderate state
00000	Does not meet requirements

. . . . . . .