

OPEL COMBO 1.6 Airco Navi NAP!



Itemno 308385
Kind Van
Specification Compact panel van
Matriculation year 2019 / 02
Mileage 133,873 km

Chassisnumber
W0VEFBHWBKJ557781

Technical condition

Remarks
airco, navi, pdc, zijdeur, nieuwe apk!
(A15)

Price € 9900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	692 kg
Own weight	1,278 kg
Gross vehicle weight	1,970 kg
Unbraked towing capacity	680 kg
Braked towing capacity, center axle	1,000 kg
Wheelbase	279 cm
Suspension type	coil spring suspension

Cabin

Cabin type	single cabin
Airconditioning	✓
Number of airbags	1
Parking assistance	Front and back
Electric windows	✓
Electric mirrors	✓
Partition	✓
GPS navigation	✓
Color	white
maintenance Guide	✓

Drivetrain

Engine capacity	55 Kw (75 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing belt
Gearbox kind	Manual
Number of Gears	5
Power steering	✓
ABS	✓
ASR	✓

Superstructure

Woodlined box	✓
Inner box length	178 cm
Inner box width	124 cm
Inner box height	119 cm
Load bed height	55 cm
Netto height	112 cm
Roof-rack	None
Sidedoors	1
Back doors	Double door

Chairs

Number of seats	2
Seat cover	cloth

Remarks

Remarks	airco, navi, pdc, zijdeur, nieuwe apk!
---------	--

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



1

2
mm

2
mm

Tire size: 195/65R15,0
coil spring suspension
Disc brakes



2

4
mm

4
mm

Tire size: 195/65R15,0
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements