

VOLKSWAGEN TRANSPORTER 2.0 TDI TDI 204 DCI

KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES



Itemno 308387
Kind Van
Specification Closed Van
Matriculation year 2018 / 04
Mileage 138,613 km

Chassisnumber
WV1ZZZ7HZJH110193

Technical condition

Remarks
dubbele cabine, DSG aut., airco, navi, leer,
(A15)

Price € 31750

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	739 kg
Own weight	2,061 kg
Gross vehicle weight	2,800 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,500 kg
Towing bracket	✓
Wheelbase	340 cm
Aluminium rims	✓
Suspension type	coil spring suspension

Cabin

Cabin type	single cabin
Cruise control	✓
Airconditioning	✓
Number of airbags	2
Rear wiper	✓
Parking assistance	Front and back
Electric windows	✓
Electric mirrors	✓
Partition	✓
GPS navigation	✓
Color	Blue
Metallic	✓

Drivetrain

Engine capacity	150 Kw (204 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing belt
Gearbox kind	Automatic
Power steering	✓
ABS	✓
ASR	✓

Superstructure

Inner box length	185 cm
Inner box width	157 cm
Inner box height	131 cm
Load bed height	60 cm
Netto height	128 cm
Roof-rack	None
Sidedoors	2
Side windows	2
Back doors	Double door

Chairs

Number of seats	5
Seat cover	leather

Remarks

Remarks	dubbele cabine, DSG aut., airco, navi, leer, 204 pk, LMV, LED, VOL!!!
---------	---

Tyres/Wheels

Sparewheel	✓
------------	---

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 255/40R19,0
coil spring suspension
Disc brakes



Tire size: 255/40R19,0
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements