
RENAULT TRAFIC 1.6 DCI



Itemno Kind Specification Matriculation year Mileage Chassisnumber

308405 Van Closed Van 2019/03 53,983 km



KLEYN KLEYN Kleyn Vans B.V.®

P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles Configuration Loading Capacity Own weight Gross vehicle weight Unbraked towing capacity Braked towing capacity, center axle Towing bracket Wheelbase Aluminium rims Suspension type

Cabin

Cabin type Cruise control Airconditioning Number of airbags Parking assistance Electric windows Electric mirrors Partition **GPS** navigation Color Metallic

Drivetrain

Engine capacity Fuel type Euro Distribution type Gearbox kind Number of Gears Power steering ABS ASR

4x2 1,305 kg 1,725 kg 3,030 kg 750 kg

2

350 cm

2,000 kg

coil spring suspension

single cabin

1 Back

Anthracite

89 Kw (121 Hp) diesel 6 Timing chain Manual 6

Superstructure

Build kind Inner box length Inner box width Inner box heigth Load bed heigth Netto height Roof-rack Sidedoors Back doors Workshop equipment

Chairs

Number of seats Seat cover

Remarks Remarks

Tyres/Wheels Sparewheel

Medium length - Standard roof 270 cm 164 cm 137 cm 55 cm 130 cm None 1 Double door

3 cloth

AC NAVI CRUISE EURO6

Contact information



info@kleyn.com Tel: +31 183 668 444

Certified and professional




Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.



Technical condition Remarks AC NAVI CRUISE EURO6 (A15) Price €17950

Dimensions



Inspection report

| Chassis | |
|-------------------------|--|
| | |
| Dashboard display codes | |
| Electrical | |
| Cabin | |
| Internal | |
| External | |
| Steering column | |
| Suspension | |
| Chassis | |
| Brakes | |
| Drivetrain | |
| Engine, general | |
| Cooling system | |
| Fuel system | |
| Exhaust system | |
| Greasing system | |
| Gearbox | |
| Clutch | |
| Drivetrain | |
| Superstructure | |
| Internal condition | |
| External condition | |
| Tyres/Wheels | |

Tyres

Contact information



info@kleyn.com Tel: +31 183 668 444

0000

KLEYN KLEYN GROUP KLEYN TRUCKS

Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Tires and axles



Legenda for inspection report Very good state Good state Reasonable state Moderate state Does not meet requirements