

MERCEDES-BENZ SPRINTER 519 DUB.CAB V6 3.0L



Itemno 308447
Kind Van
Specification Open with sideboards
Matriculation year 2019 / 03
Mileage 127,330 km

Chassisnumber
WDB9072551N042307

Technical condition

Remarks
Dubbel Cabine 3.0Ltr V6 190Pk Dubbellucht
(A15)

Price € 33900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Twin tires ✓
Loading Capacity 857 kg
Own weight 2,643 kg
Gross vehicle weight 3,500 kg
Unbraked towing capacity 750 kg
Braked towing capacity, center axle 3,500 kg
Wheelbase 433 cm
Suspension type spring suspension

Cabin

Cabin type double cabin
Tacho ✓
Number of airbags 1
Parking assistance None
Electric windows ✓
Electric mirrors ✓
GPS navigation ✓
Color Yellow

Drivetrain

Engine capacity 140 Kw (190 Hp)
Fuel type diesel
Euro 6
Distribution type Timing chain
Gearbox kind Manual
Power steering ✓
ABS ✓
ASR ✓

Superstructure

Inner box length 361 cm
Inner box width 213 cm
Inner box height 40 cm
Load bed height 101 cm
Roof-rack None
Sidedoors 2
Side windows 2
Back doors taillift

Chairs

Number of seats 7
Seat cover leather

Remarks

Remarks Dubbel Cabine 3.0Ltr V6 190Pk
Dubbellucht Euro6!

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Tacho

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



1
Tire size: 205/75R16,0
spring suspension
Disc brakes



2
Tire size: 205/75R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements