

## OPEL VIVARO 1.6 L2H1 Airco Navi NAP!



Itemno 308471  
Kind Van  
Specification Closed Van  
Matriculation year 2018 / 07  
Mileage 99,105 km

**Chassisnumber**  
W0VF7D605JV642602

Technical condition 

**Remarks**  
L2H1 Airco Navi Trekhaak Imperiaal-Trap  
( A15 )

**Price €14900**

# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®  
P.O. Box 3  
4214 ZJ Vuren  
Zeiving 12  
4214 KT Vuren  
The Netherlands

IBAN: NL32RABO0317847430  
SWIFT/BIC: RABONL2U

KvK 11044363  
BTW/VAT NL807901337B01

## Equipment

### Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	1,305 kg
Own weight	1,705 kg
Gross vehicle weight	3,010 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,000 kg
Towing bracket	
Wheelbase	350 cm
Suspension type	coil spring suspension

### Cabin

Cabin type	single cabin
Cruise control	
Airconditioning	
Number of airbags	2
Parking assistance	Back
Electric windows	
Partition	
GPS navigation	
Color	white
maintenance Guide	

### Drivetrain

Engine capacity	92 Kw (125 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing chain
Gearbox kind	Manual
Number of Gears	6
Power steering	
ABS	
ASR	

### Superstructure

Woodlined box	
Inner box length	294 cm
Inner box width	166 cm
Inner box height	136 cm
Load bed height	57 cm
Netto height	130 cm
Rear step	
Roof-rack	with roll and stairs
Sidedoors	1
Back doors	Double door

### Chairs

Number of seats	2
Seat cover	cloth

### Remarks

Remarks	L2H1 Airco Navi Trekhaak Imperiaal-Trap NAP!
---------	--

### Tyres/Wheels

Sparewheel

### Contact information




info@kleyn.com  
Tel: +31 183 668 444

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

## Inspection report

### Chassis

Dashboard display codes

Electrical

### Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

### Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

### Superstructure

Internal condition

External condition

### Tyres/Wheels

Tyres

## Tires and axles



Tire size: 205/65R16,0  
coil spring suspension  
Disc brakes



Tire size: 205/65R16,0  
coil spring suspension  
Disc brakes

### Contact information



info@kleyn.com

Tel: +31 183 668 444

### Legenda for inspection report

Very good state  
 Good state  
 Reasonable state  
 Moderate state  
 Does not meet requirements