

MERCEDES-BENZ VITO 116 CDI



Itemno 308484
Kind Van
Specification Closed Van
Matriculation year 2021 / 02
Mileage 83,513 km

Chassisnumber
W1V44760513828277

Technical condition

Remarks
XL! AC CAMERA EURO6!
(A15)

Price €25950

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	793 kg
Own weight	2,007 kg
Gross vehicle weight	2,800 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,000 kg
Towing bracket	
Wheelbase	343 cm
Suspension type	coil spring suspension

Cabin

Cabin type	single cabin
Cruise control	
Airconditioning	
Number of airbags	2
Parking assistance	Front and back
Electric windows	
Electric mirrors	
Partition	
GPS navigation	
Color	white
Heated mirrors	
Reversing camera	

Drivetrain

Engine capacity	120 Kw (163 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing chain
Gearbox kind	Manual
Number of Gears	6
Power steering	
ABS	
ASR	

Superstructure

Build kind	Medium length - Standard roof
Inner box length	272 cm
Inner box width	165 cm
Inner box height	134 cm
Load bed height	53 cm
Netto height	123 cm
Roof-rack	None
Sidedoors	1
Back doors	Double door
Workshop equipment	

Chairs

Number of seats	2
Seat cover	cloth

Remarks

Remarks	XL! AC CAMERA EURO6!
---------	----------------------

Tyres/Wheels

Sparewheel

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



1

Tire size: 205/65R16,0
coil spring suspension
Disc brakes



2

Tire size: 205/65R16,0
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements