

MERCEDES-BENZ SPRINTER 319 CDI



Itemno 308504
 Kind Van
 Specification Closed Van
 Matriculation year 2023 / 12
 Mileage 6 km
Chassisnumber
 W1V3MBFZ7PP580120
 Technical condition 
Remarks
 AC AUTOMAAT MBUX10 EURO6 NIEUW
 (A15)

Price € 48950

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
 P.O. Box 3
 4214 ZJ Vuren
 Zeiving 12
 4214 KT Vuren
 The Netherlands

IBAN: NL32RABO0317847430
 SWIFT/BIC: RABONL2U

KvK 11044363
 BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
 Configuration 4x2
 Wheelbase 367 cm
 Suspension type spring suspension

Cabin

Cruise control ✓
 Airconditioning ✓
 Number of airbags 1
 Parking assistance None
 Electric windows ✓
 Electric mirrors ✓
 Partition ✓
 GPS navigation ✓
 Color Black
 Metallic ✓
 maintenance Guide ✓
 Heated mirrors ✓
 Reversing camera ✓

Drivetrain

Engine capacity 140 Kw (190 Hp)
 Fuel type diesel
 Euro 6
 Distribution type Timing chain
 Gearbox kind Automatic
 Power steering ✓
 ABS ✓
 ASR ✓

Superstructure

Build kind Medium length - High roof
 Inner box length 333 cm
 Inner box width 177 cm
 Inner box height 196 cm
 Load bed height 68 cm
 Roof-rack None
 Back doors Double door

Chairs

Number of seats 3
 Seat cover cloth
 Comfort seat left

Remarks

Remarks AC AUTOMAAT MBUX10
 EURO6 NIEUW

Tyres/Wheels

Sparewheel ✓
 Spare tire profile 8 mm

Contact information




info@kleyn.com
 Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes 

Electrical 

Cabin

Internal 

External 

Steering column 

Suspension 

Chassis 

Wheelsuspension 

Brakes 

Drivetrain

Engine, general 

Cooling system 

Fuel system 

Exhaust system 

Greasing system 

Gearbox 

Clutch 

Drivetrain 

Superstructure

Superstructure 

Internal condition 

External condition 

Tyres/Wheels

Tyres 

Tires and axles



Tire size: 235/65R16,0
spring suspension
Disc brakes



Tire size: 235/65R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

-  Very good state
-  Good state
-  Reasonable state
-  Moderate state
-  Does not meet requirements