

## MERCEDES-BENZ SPRINTER 314 CDI L3H2 MAXI



Itemno 308557  
Kind Van  
Specification Closed Van  
Matriculation year 2019 / 03  
Mileage 109,542 km

**Chassisnumber**  
WDB9076351P088730

Technical condition

### Remarks

( A15 )

**Price €26900**

# KLEYN VANS

**KLEYN** GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®  
P.O. Box 3  
4214 ZJ Vuren  
Zeiving 12  
4214 KT Vuren  
The Netherlands

IBAN: NL32RABO0317847430  
SWIFT/BIC: RABONL2U

KvK 11044363  
BTW/VAT NL807901337B01

## Equipment

### Chassis

Number of axles 2  
Configuration 4x2

### Cabin

Cabin type single cabin  
Cruise control  
Airconditioning  
Parking assistance None  
Electric windows  
Electric mirrors  
Partition  
maintenance Guide  
Heated mirrors  
Reversing camera

### Drivetrain

Engine capacity 100 Kw (136 Hp)  
Fuel type diesel  
Euro 6  
Distribution type Timing chain  
Gearbox kind Manual  
Number of Gears 6  
Power steering  
ABS  
ASR

### Superstructure

Build kind Extra Long - High roof  
Roof-rack None  
Sidedoors 1  
Back doors Double door

### Chairs

Number of seats 3  
Seat cover cloth

### Contact information



info@kleyn.com  
Tel: +31 183 668 444

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN VANS

**KLEYN** **KLEYN** **KLEYN** **KLEYN**  
GROUP TRUCKS TRAILERS SERVICES

Kleyn Vans B.V.®  
P.O. Box 3  
4214 ZJ Vuren  
Zeiving 12  
4214 KT Vuren  
The Netherlands

IBAN: NL32RABO0317847430  
SWIFT/BIC: RABONL2U

KvK 11044363  
BTW/VAT NL807901337B01

## Inspection report

### Chassis

Dashboard display codes

Electrical

### Cabin

Internal

External

Steering column

Suspension

Chassis

Wheelsuspension

Brakes

### Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

### Superstructure

Superstructure

Internal condition

External condition

### Tyres/Wheels

Tyres

## Tires and axles



Tire size: 0/0R0,0



Tire size: 0/0R0,0

### Contact information



info@kleyn.com  
Tel: +31 183 668 444

### Legenda for inspection report

Very good state  
 Good state  
 Reasonable state  
 Moderate state  
 Does not meet requirements