

VOLKSWAGEN CRAFTER 2.0 2.0 TDI 140 DSG L3H3



Itemno 308558
Kind Van
Specification Closed Van
Matriculation year 2023 / 11
Mileage 725 km

Chassisnumber
WV1ZZZSY0R9017111

Technical condition

Remarks
CAMERA / CARPLAY / COMFORTLINE
(A15)

Price €39950



Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
Configuration 4x2

Cabin

Cruise control
Airconditioning
Parking assistance Front and back
Electric windows
Electric mirrors
Partition
Color white
maintenance Guide
Reversing camera

Drivetrain

Engine capacity 100 Kw (136 Hp)
Fuel type diesel
Euro 6
Distribution type Timing chain
Gearbox kind Automatic
Number of Gears 7
Power steering
ABS
ASR

Superstructure

Build kind Medium length - High roof
Rear step
Roof-rack None
Sidedoors 1
Back doors Double door

Chairs

Number of seats 3
Seat cover cloth

Remarks

Remarks CAMERA / CARPLAY / COMFORTLINE NIEUW!!

Contact information



info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions




Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes 

Electrical 

Cabin

Internal 

External 

Steering column 

Suspension 

Chassis 

Wheelsuspension 

Brakes 

Drivetrain

Engine, general 

Cooling system 

Fuel system 

Exhaust system 

Greasing system 


Gearbox 

Clutch 

Drivetrain 

Superstructure

Superstructure 

Internal condition 

External condition 

Tyres/Wheels

Tyres 

Tires and axles



Tire size: 0/0R0,0



Tire size: 0/0R0,0

Contact information



info@kleyn.com
Tel: +31 183 668 444

Legenda for inspection report

-  Very good state
-  Good state
-  Reasonable state
-  Moderate state
-  Does not meet requirements