FORD TRANSIT CONNECT 1.6 TDCI L2H1



Itemno Kind Specification Matriculation year Mileage Chassisnumber WF0SXXWPGSFU30815

308601 Van Compact panel van 2016 / 02 143,615 km



Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles Configuration Own weight Gross vehicle weight Towing bracket Wheelbase Suspension type

Cabin

Cabin type Cruise control Airconditioning Parking heater Number of airbags Parking assistance Electric windows Electric mirrors Partition Color maintenance Guide Heated mirrors

Drivetrain

Engine capacity Fuel type Euro Distribution type Gearbox kind Number of Gears Power steering ABS ASR

2 4x2 1,560 kg 2,395 kg

306 cm coil spring suspension

single cabin

6 None

white

70 Kw (95 Hp) diesel 5 Timing belt Manual 5

Superstructure

Inner box length Inner box width Inner box heigth Load bed heigth Netto height Roof-rack Back doors

Chairs

Number of seats Seat cover

Remarks

Remarks

195 cm 129 cm 127 cm 60 cm 112 cm standard Double door

3 cloth

lang,airco, navi, pdc ,trekhaak

Contact information




info@kleyn.com Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



Inspection report

Chassis	
Dashboard display codes	
Electrical	
Cabin	
Internal	
External	000
Steering column	i i i i i i i i i i i i i i i i i i i
Suspension	
Chassis	
Brakes	
Drivetrain	
Engine, general	
Cooling system	
Fuel system	
Exhaust system	
Greasing system	
Gearbox	
Clutch	
Drivetrain	
Superstructure	
Internal condition	
External condition	
Tyres/Wheels	

Tyres

Contact information



info@kleyn.com Tel: +31 183 668 444

VANS

Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Tires and axles



Legenda for inspection report Very good state Good state Reasonable state

Moderate state

O O O Does not meet requirements