

## MERCEDES-BENZ SPRINTER 314 BI-TEMP Koelwag



Itemno 308637  
Kind Van  
Specification Frigo  
Matriculation year 2019 / 07  
Mileage 151,194 km

**Chassisnumber**  
WDB9066331P602603

Technical condition

**Remarks**  
BI-TEMP Koelwagen/ FRIGO D/N L2H2  
( A15 )

**Price €32900**

# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®  
P.O. Box 3  
4214 ZJ Vuren  
Zeiving 12  
4214 KT Vuren  
The Netherlands

IBAN: NL32RABO0317847430  
SWIFT/BIC: RABONL2U

KvK 11044363  
BTW/VAT NL807901337B01

## Equipment

### Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	945 kg
Own weight	2,555 kg
Gross vehicle weight	3,500 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,000 kg
Towing bracket	
Wheelbase	367 cm
Suspension type	spring suspension

### Cabin

Cabin type	single cabin
Airconditioning	
Number of airbags	1
Parking assistance	None
Coloured windows	
Electric windows	
Electric mirrors	
Partition	
Color	white
Heated mirrors	

### Drivetrain

Engine capacity	105 Kw (143 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing chain
Gearbox kind	Manual
Number of Gears	6
Power steering	
ABS	
ASR	

### Superstructure

Inner box length	306 cm
Inner box width	156 cm
Inner box height	178 cm
Load bed height	70 cm
Roof-rack	None
Back doors	Double door

### Chairs

Number of seats	3
Seat cover	cloth

### Refrigeration unit

Enginemake frigo-unit	Carrier
Enginetype frigo-unit	xarios 350mt
Enginetype frigo-unit	fuel and electrical
Type of cooling	Cooling and freezing
Day/night cooling	day and night cooling

### Remarks

Remarks	BI-TEMP Koelwagen/ FRIGO D/N L2H2 Airco Trekhaak Euro6!
---------	---

### Tyres/Wheels

Sparewheel

### Contact information




info@kleyn.com  
Tel: +31 183 668 444

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®  
P.O. Box 3  
4214 ZJ Vuren  
Zeiving 12  
4214 KT Vuren  
The Netherlands

IBAN: NL32RABO0317847430  
SWIFT/BIC: RABONL2U

KvK 11044363  
BTW/VAT NL807901337B01

## Inspection report

### Chassis

Dashboard display codes

Electrical

### Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

### Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

### Superstructure

Internal condition

External condition

### Refrigeration unit

Systems

### Tyres/Wheels

Tyres

## Tires and axles



1  
Tire size: 235/65R16,0  
spring suspension  
Disc brakes



2  
Tire size: 235/65R16,0  
spring suspension  
Disc brakes

### Contact information



info@kleyn.com  
Tel: +31 183 668 444

### Legenda for inspection report

Very good state  
 Good state  
 Reasonable state  
 Moderate state  
 Does not meet requirements