

VOLKSWAGEN TRANSPORTER 2.0 TDI



Itemno 308659
Kind Van
Specification Closed Van
Matriculation year 2017 / 09
Mileage 241,253 km

Chassisnumber
WV1ZZZ7HZJH038537

Technical condition

Remarks

(A15)



Price €7900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Loading Capacity 499 kg
Own weight 1,866 kg
Gross vehicle weight 2,365 kg
Unbraked towing capacity 750 kg
Braked towing capacity, center axle 2,200 kg
Towing bracket
Wheelbase 340 cm
Suspension type coil spring suspension

Cabin

Cabin type single cabin
Cruise control
Airconditioning
Number of airbags 2
Parking assistance None
Coloured windows
Electric windows
Electric mirrors
Partition
GPS navigation
Color white
Heated mirrors
Reversing camera

Drivetrain

Engine capacity 75 Kw (102 Hp)
Fuel type diesel
Euro 6
Distribution type Timing belt
Gearbox kind Manual
Number of Gears 5
Power steering
ABS
ASR

Superstructure

Inner box length 283 cm
Inner box width 163 cm
Inner box height 138 cm
Load bed height 59 cm
Roof-rack None
Back doors Double door

Chairs

Number of seats 2
Seat cover cloth

Tyres/Wheels

Sparewheel

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 205/65R16,0
coil spring suspension
Disc brakes



Tire size: 205/65R16,0
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements