

MERCEDES-BENZ SPRINTER 316 CDI



Itemno 308708
Kind Van
Specification Frigo
Matriculation year 2018 / 07
Mileage 370,825 km

Chassisnumber
WDB9076351P012911

Technical condition

Remarks
AC AUTOMAAT EURO6 KOELWAGEN
(A15)

Price €15950

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	663 kg
Own weight	2,837 kg
Gross vehicle weight	3,500 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,000 kg
Wheelbase	433 cm
Suspension type	spring suspension

Cabin

Cabin type	single cabin
Cruise control	
Airconditioning	
Number of airbags	2
Parking assistance	None
Coloured windows	
Electric windows	
Electric mirrors	
Partition	
Color	white
Heated mirrors	
Reversing camera	

Drivetrain

Engine capacity	120 Kw (163 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing chain
Gearbox kind	Automatic
Power steering	
ABS	
ASR	

Superstructure

Build kind	Extra Long - High roof
Inner box length	419 cm
Inner box width	165 cm
Inner box height	183 cm
Load bed height	72 cm
Rear step	
Roof-rack	None
Back doors	Double door

Chairs

Number of seats	3
Seat cover	cloth

Refrigeration unit

Enginetype frigo-unit	Carrier
Enginetype frigo-unit	xarios 350
Enginetype frigo-unit	electrical
Type of cooling	Cooling
Day/night cooling	day cooling

Remarks

Remarks	AC AUTOMAAT EURO6 KOELWAGEN CARRIER EXPORT
---------	--

Tyres/Wheels

Sparewheel

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Refrigeration unit

Systems

Tyres/Wheels

Tyres

Tires and axles



Tire size: 235/65R16,0
spring suspension
Disc brakes



Tire size: 235/65R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements