

MERCEDES-BENZ G-KLASSE G63 AMG FULL-OPTIC



Itemno 308827
Kind Passenger Car
Specification
Matriculation year 2016 / 05
Mileage 159,488 km

Chassisnumber
WDB4632721X261735

Technical condition

Remarks
G63 AMG BRABUS-Pakket 22"-Maybach
(A15)

Price € 84900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
Configuration 4x4
Wheelbase 285 cm
Aluminium rims ✓
Suspension type coil spring suspension

Cabin

Cruise control ✓
Airconditioning ✓
Number of airbags 6
Rear wiper ✓
Parking assistance Front and back
Electric windows ✓
Electric mirrors ✓
GPS navigation ✓
Color Anthracite
Heated mirrors ✓
Reversing camera ✓

Drivetrain

Engine capacity (0 Hp)
Fuel type petrol
Distribution type Timing chain
Gearbox kind Automatic
Power steering ✓
ABS ✓
ASR ✓

Superstructure

Inner box length 92 cm
Inner box width 150 cm
Inner box height 116 cm
Load bed height 73 cm
Netto height 114 cm
Roof-rack None
Back doors Single door

Chairs

Number of seats 5
Seat cover leather
Comfort seat left and right

Remarks

Remarks
G63 AMG BRABUS-Pakket
22"-Maybach
Harman-Kardon-Sound
Stoel-Koeling Etc.

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 285/40R22,0
coil spring suspension
Disc brakes



Tire size: 285/40R22,0
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements