CITROEN JUMPER 2.0 BLUEHDI 130 KIPPER



Itemno 308937 Kind Van Specification Tipper Matriculation year 2019 / 09 Mileage 55,729 km

Chassisnumber VF7YC2MAU12L50259

kipper, airco, 55 dkm.

Technical condition

Remarks

(A15)





Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles Configuration 4x2 2,260 kg Own weight 3,500 kg Gross vehicle weight

Towing bracket

Wheelbase 345 cm

Suspension type spring suspension

Cabin

Cabin type single cabin

Cruise control

Airconditioning

Number of airbags Parking assistance None

Electric windows

Electric mirrors

white Color

maintenance Guide Heated mirrors

Drivetrain

96 Kw (130 Hp) Engine capacity

Fuel type diesel Distribution type Timing belt Gearbox kind Manual Number of Gears

Power steering

ABS ASR

Superstructure

Tipping possibilities 1 side Inner box length 321 cm Inner box width 201 cm 35 cm Inner box heigth 90 cm Load bed heigth Roof-rack None Back doors taillift

Chairs

Number of seats 3 Seat cover cloth

Remarks

Remarks kipper, airco, 55 dkm.

Tyres/Wheels

Sparewheel

Spare tire profile 7 mm

Contact information



info@kleyn.com Tel: +31 183 668 444

Certified and professional

















Dimensions



Tyres/Wheels

Tyres

KLEYN VANS

GROUP KLEYN KLEYN TRJCKS

KLEYN



Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Steering column

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Exhaust system

Greasing system

Superstructure

Internal condition

External condition

Tipper

Tires and axles



Tire size: 215/70R15,0 coil spring suspension Disc brakes



Tire size: 215/70R15,0 spring suspension Disc brakes

Contact information



info@kleyn.com Tel: +31 183 668 444

Legenda for inspection report

Very good state
Good state
Reasonable state

Moderate state

Does not meet requirements