

## MERCEDES-BENZ SPRINTER 516 DUB.CAB Open-L



Itemno 308973  
Kind Van  
Specification Open with sideboards  
Matriculation year 2017 / 03  
Mileage 127,911 km

**Chassisnumber**  
WDB9062531N702654

Technical condition

**Remarks**  
Dubbel Cabine Open-Laadbak Dubbellucht  
( A15 )

**Price € 21900**

# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®  
P.O. Box 3  
4214 ZJ Vuren  
Zeiving 12  
4214 KT Vuren  
The Netherlands

IBAN: NL32RABO0317847430  
SWIFT/BIC: RABONL2U

KvK 11044363  
BTW/VAT NL807901337B01

## Equipment

### Chassis

|                                     |                   |
|-------------------------------------|-------------------|
| Number of axles                     | 2                 |
| Configuration                       | 4x2               |
| Loading Capacity                    | 900 kg            |
| Own weight                          | 2,600 kg          |
| Gross vehicle weight                | 3,500 kg          |
| Unbraked towing capacity            | 750 kg            |
| Braked towing capacity, center axle | 2,000 kg          |
| Towing bracket                      | ✓                 |
| Wheelbase                           | 367 cm            |
| Suspension type                     | spring suspension |

### Cabin

|                    |              |
|--------------------|--------------|
| Cabin type         | double cabin |
| Tacho              | ✓            |
| Parking heater     | ✓            |
| Number of airbags  | 1            |
| Parking assistance | None         |
| Electric windows   | ✓            |
| Electric mirrors   | ✓            |
| Color              | white        |
| maintenance Guide  | ✓            |
| Heated mirrors     | ✓            |

### Drivetrain

|                   |                 |
|-------------------|-----------------|
| Engine capacity   | 120 Kw (163 Hp) |
| Fuel type         | diesel          |
| Euro              | 6               |
| Distribution type | Timing chain    |
| Gearbox kind      | Manual          |
| Number of Gears   | 6               |
| Power steering    | ✓               |
| ABS               | ✓               |
| ASR               | ✓               |

### Superstructure

|                  |          |
|------------------|----------|
| Inner box length | 280 cm   |
| Inner box width  | 215 cm   |
| Inner box height | 31 cm    |
| Load bed height  | 91 cm    |
| Roof-rack        | None     |
| Back doors       | taillift |

### Chairs

|                 |       |
|-----------------|-------|
| Number of seats | 6     |
| Seat cover      | cloth |

### Remarks

|         |                                                                    |
|---------|--------------------------------------------------------------------|
| Remarks | Dubbel Cabine Open-Laadbak<br>Dubbellucht Trekhaak 163Pk<br>Euro6! |
|---------|--------------------------------------------------------------------|

### Contact information




info@kleyn.com  
Tel: +31 183 668 444

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

## Inspection report

### Chassis

Tacho

Dashboard display codes

Electrical

### Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

### Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

### Superstructure

Internal condition

External condition

### Tyres/Wheels

Tyres

## Tires and axles



Tire size: 205/75R16,0  
spring suspension  
Disc brakes



Tire size: 205/75R16,0  
spring suspension  
Disc brakes

### Contact information



info@kleyn.com

Tel: +31 183 668 444

### Legenda for inspection report

Very good state  
 Good state  
 Reasonable state  
 Moderate state  
 Does not meet requirements