

VOLKSWAGEN TRANSPORTER 2.0 TDI T6.1 L1H1 L



Itemno 308995
Kind Van
Specification Closed Van
Matriculation year 2020 / 02
Mileage 97,197 km

Chassisnumber
WV1ZZZ7HZLH029172

Technical condition

Remarks
T6.1 L1H1 LED Automaat 150Pk Euro6
(A15)

Price €29800

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	940 kg
Own weight	1,860 kg
Gross vehicle weight	2,800 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,500 kg
Towing bracket	
Wheelbase	300 cm
Aluminium rims	
Suspension type	coil spring suspension

Cabin

Cabin type	single cabin
Airconditioning	
Number of airbags	2
Rear wiper	
Parking assistance	Front and back
Coloured windows	
Electric windows	
Electric mirrors	
Color	Black
Metallic	
maintenance Guide	
Heated mirrors	

Drivetrain

Engine capacity	110 Kw (149 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing belt
Gearbox kind	Automatic
Power steering	
ABS	
ASR	

Superstructure

Inner box length	242 cm
Inner box width	163 cm
Inner box height	137 cm
Load bed height	60 cm
Roof-rack	None
Back doors	taillift

Chairs

Number of seats	2
Seat cover	cloth

Remarks

Remarks	T6.1 L1H1 LED Automaat 150Pk Euro6 1eEigenaar!
---------	--

Tyres/Wheels

Sparewheel

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



1

Tire size: 235/55R17,0
coil spring suspension
Disc brakes



2

Tire size: 235/55R17,0
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements