

MERCEDES-BENZ SPRINTER 314 L2H2 BI-TEMP FR



Itemno 309043
Kind Van
Specification Frigo
Matriculation year 2017 / 05
Mileage 181,922 km

Chassisnumber
WDB9066331P396400

Technical condition

Remarks
BI-TEMP Koelwagen 2-Compartmenten
(A15)

Price €29900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	951 kg
Own weight	2,549 kg
Gross vehicle weight	3,500 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,000 kg
Wheelbase	367 cm
Suspension type	spring suspension

Cabin

Cabin type	single cabin
Cruise control	
Number of airbags	1
Parking assistance	None
Electric windows	
Electric mirrors	
Partition	
GPS navigation	
Color	white
Reversing camera	

Drivetrain

Engine capacity	105 Kw (143 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing chain
Gearbox kind	Manual
Power steering	
ABS	
ASR	

Superstructure

Inner box length	305 cm
Inner box width	155 cm
Inner box height	178 cm
Load bed height	64 cm
Netto height	169 cm
Rear step	
Roof-rack	None
Sidedoors	1
Back doors	Double door

Chairs

Number of seats	3
Seat cover	cloth

Refrigeration unit

Enginemake frigo-unit	Carrier
Enginetype frigo-unit	350 mt
Enginetype frigo-unit	electrical
Type of cooling	Cooling
Day/night cooling	day and night cooling

Remarks

Remarks	BI-TEMP Koelwagen 2-Compartmenten Camera 143Pk Euro6!
---------	---

Tyres/Wheels

Sparewheel

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Refrigeration unit

Systems

Tyres/Wheels

Tyres

Tires and axles



Tire size: 235/65R16,0
spring suspension
Disc brakes



Tire size: 235/65R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements