VOLKSWAGEN TRANSPORTER 2.0 TDI L1H1 150Pk



Itemno 309088 Kind Van Specification Closed Van Matriculation year 2018 / 12 Mileage 127,034 km


Chassisnumber WV1ZZZ7HZKH063050

Technical condition









Price €21750

Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles Configuration 4x2 Loading Capacity 911 kg Own weight 1,889 kg Gross vehicle weight 2,800 kg Unbraked towing capacity 750 kg Braked towing capacity, center 2,500 kg

Towing bracket

Wheelbase 300 cm

Suspension type coil spring suspension

Cabin

Cabin type single cabin

Cruise control

Airconditioning Number of airbags

Parking assistance Front and back

Coloured windows Electric windows Electric mirrors Partition

GPS navigation

white

maintenance Guide Heated mirrors

Drivetrain

Engine capacity 110 Kw (149 Hp)

Fuel type diesel Euro

Distribution type Timing belt Gearbox kind Automatic

Power steering

ABS ASR

Superstructure

Inner box length 244 cm Inner box width 163 cm 141 cm Inner box heigth Load bed heigth 60 cm Roof-rack None Back doors Double door

Chairs

Number of seats 3 Seat cover cloth

Remarks

Remarks L1H1 150Pk Airco Automaat

Business-Line-Plus Navi Euro6!

Tyres/Wheels

Sparewheel

Contact information



info@kleyn.com Tel: +31 183 668 444

Certified and professional














Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KL = YN VANS

EYN KLEYN K

(LEYN TRAILERS



Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general 00000 33330 Cooling system 00000 Fuel system Exhaust system 00000 Greasing system Gearbox 3330 Clutch 00000 Drivetrain 33330

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 205/65R16,0 coil spring suspension Disc brakes



Tire size: 205/65R16,0 coil spring suspension Disc brakes

Contact information



info@kleyn.com Tel: +31 183 668 444

Legenda for inspection report

Very good state
Good state
Reasonable state

Moderate state

Does not meet requirements