

MERCEDES-BENZ VITO 111 CDI



Itemno 309107
Kind Van
Specification Closed Van
Matriculation year 2016 / 09
Mileage 132,886 km

Chassisnumber
WDF44760513145539

Technical condition

Remarks
XL DUBBEL CABINE AIRCO!
(A15)



Price €15950

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	871 kg
Own weight	1,929 kg
Gross vehicle weight	2,800 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,000 kg
Wheelbase	343 cm
Suspension type	coil spring suspension

Cabin

Cabin type	double cabin
Cruise control	
Airconditioning	
Number of airbags	2
Rear wiper	
Parking assistance	None
Coloured windows	
Electric windows	
Electric mirrors	
Partition	
Color	white
Heated mirrors	

Drivetrain

Engine capacity	84 Kw (114 Hp)
Fuel type	diesel
Euro	5
Distribution type	Timing chain
Gearbox kind	Manual
Number of Gears	5
Power steering	
ABS	
ASR	

Superstructure

Build kind	Extra Long - High roof
Inner box length	184 cm
Inner box width	174 cm
Inner box height	133 cm
Load bed height	54 cm
Netto height	125 cm
Roof-rack	standard
Sidedoors	1
Side windows	2
Back doors	Double door

Chairs

Number of seats	5
Seats configuration	2+3
Seat cover	skai

Remarks

Remarks	XL DUBBEL CABINE AIRCO!
---------	-------------------------

Tyres/Wheels

Sparewheel

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



1
Tire size: 205/65R16,0
coil spring suspension
Disc brakes



2
Tire size: 205/65R16,0
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements