# M.A.N. TGE 2.140



Itemno309135KindVanSpecificationClosed VanMatriculation year2017 / 06Mileage240,564 km

Chassisnumber WMA01VUY2J9001077

**Price €14950** 

Technical condition **Remarks**AIRCO EURO6!

(A15)







Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

# **Equipment**

### Chassis

Number of axles 2
Configuration 4x2
Loading Capacity 1,069 kg
Own weight 1,931 kg
Gross vehicle weight 3,000 kg
Unbraked towing capacity 750 kg
Braked towing capacity, center 3,000 kg

Towing bracket

Wheelbase 364 cm

Suspension type spring suspension

### Cabin

Cabin type single cabin

Cruise control

Airconditioning
Number of airbags

Parking assistance Front and back

Electric windows
Electric mirrors

Partition GPS navigation

O O I avigation

Color Anthracite

Metallic

Heated mirrors Reversing camera

# Drivetrain

Engine capacity 103 Kw (140 Hp)

Fuel type diesel Euro 6

Distribution type Timing belt
Gearbox kind Manual
Number of Gears 6

Power steering

ABS ASR

## Superstructure

Build kind Medium length - Standard roof Inner box length 325 cm 177 cm Inner box width 174 cm Inner box heigth Load bed heigth 60 cm 158 cm Netto height Roof-rack None Back doors Double door

#### Chairs

Number of seats 2
Seat cover cloth
Comfort seat left

## Remarks

Remarks AIRCO EURO6!

## Tyres/Wheels

Sparewheel

#### **Contact information**



info@kleyn.com Tel: +31 183 668 444

### Certified and professional












Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

# **Dimensions**





LEYN KLEYN K

KLEYN



Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

# **Inspection report**

### Chassis

Dashboard display codes

Electrical

## Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

# Drivetrain

Engine, general 33330 Cooling system 00000 Fuel system 0000 Exhaust system 0000 Greasing system Gearbox 3330 Clutch 00000 Drivetrain 33330

### Superstructure

Internal condition

External condition

# Tyres/Wheels

Tyres

# Tires and axles



Tire size: 205/75R16,0 coil spring suspension Disc brakes



Tire size: 205/75R16,0 spring suspension Disc brakes

#### **Contact information**



info@kleyn.com Tel: +31 183 668 444

### Legenda for inspection report

Very good state
Good state
Reasonable state

Moderate state

Does not meet requirements