

VOLKSWAGEN CRAFTER 2.0 TDI 136 L2H1



Itemno 309153
Kind Van
Specification Closed Van
Matriculation year 2016 / 04
Mileage 227,840 km

Chassisnumber
WV1ZZZ2EZG6032066

Technical condition 

Remarks
L2H1, airco, navi, trekhaak, camera
(A15)

Price €9700

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Own weight 2,205 kg
Gross vehicle weight 3,200 kg
Towing bracket
Wheelbase 367 cm
Suspension type spring suspension

Cabin

Cabin type single cabin
Cruise control
Airconditioning
Number of airbags 2
Parking assistance Front and back
Coloured windows
Electric windows
Electric mirrors
Partition
Color Yellow
Heated mirrors
Reversing camera

Drivetrain

Engine capacity 100 Kw (136 Hp)
Fuel type diesel
Euro 5
Distribution type Timing chain
Gearbox kind Manual
Number of Gears 6
Power steering
ABS
ASR

Superstructure

Inner box length 331 cm
Inner box width 176 cm
Inner box height 169 cm
Load bed height 65 cm
Rear step
Roof-rack None
Back doors Double door

Chairs

Number of seats 3
Seat cover cloth

Remarks

Remarks L2H1, airco, navi, trekhaak, camera

Tyres/Wheels

Sparewheel

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



1

Tire size: 235/65R16,0
spring suspension
Disc brakes



2

Tire size: 235/65R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements