FORD TRANSIT CUSTOM 2.0 TDCI L1H1



Itemno Kind Specification Matriculation year Mileage Chassisnumber WF0YXXTTGYHD56657

309175 Van Closed Van 2018/01 56,324 km



Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles Configuration Loading Capacity Own weight Gross vehicle weight Unbraked towing capacity Braked towing capacity, center axle Towing bracket Wheelbase Suspension type

Cabin

Cabin type Cruise control Airconditioning Number of airbags Parking assistance Electric windows Electric mirrors Partition Color maintenance Guide Heated mirrors Reversing camera

Drivetrain

Engine capacity Fuel type Euro Distribution type Gearbox kind Number of Gears Power steering ABS ASR

4x2 824 kg 1,916 kg 2,740 kg 750 kg 2,350 kg

2

293 cm spring suspension

single cabin

2 Front and back

white

77 Kw (105 Hp) diesel 6 Timing chain Manual 6

Superstructure

NAP

Inner box length Inner box width Inner box heigth Load bed heigth Netto height Roof-rack Sidedoors Back doors

Chairs

Number of seats Seat cover

Remarks Remarks

Tyres/Wheels

Sparewheel

242 cm 166 cm 142 cm 58 cm 133 cm None 1 Double door

3 cloth

L1H1, airco, navi, pdc, trekhaak, 56 dkm.!!

Contact information




info@kleyn.com Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



Inspection report

Chassis	
Dashboard display codes	
Electrical	
Cabin	
Internal	
External	
Steering column	
Suspension	
Chassis	
Brakes	
Drivetrain	
Engine, general	
Cooling system	
Fuel system	
Exhaust system	
Greasing system	
Gearbox	
Clutch	
Drivetrain	
Superstructure	
Internal condition	
External condition	
Tyres/Wheels	

Tyres

Contact information



info@kleyn.com Tel: +31 183 668 444

Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Tires and axles



Legenda for inspection report Very good state Good state Reasonable state Moderate state Does not meet requirements