

## MERCEDES-BENZ VIANO 3.0 CDI



Itemno 309231  
Kind Van  
Specification Closed Van  
Matriculation year 2012 / 01  
Mileage 300,832 km

**Chassisnumber**  
WDF63981313713181

Technical condition

**Remarks**  
DUBBEL CABINE V6 3.0 LTR VOLLL  
( A15 )



**Price €14950**

# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®  
P.O. Box 3  
4214 ZJ Vuren  
Zeiving 12  
4214 KT Vuren  
The Netherlands

IBAN: NL32RABO0317847430  
SWIFT/BIC: RABONL2U

KvK 11044363  
BTW/VAT NL807901337B01

## Equipment

### Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	760 kg
Own weight	2,290 kg
Gross vehicle weight	3,050 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,500 kg
Towing bracket	
Wheelbase	320 cm
Suspension type	air suspension

### Cabin

Cabin type	double cabin
Cruise control	
Airconditioning	
Parking heater	
Number of airbags	2
Rear wiper	
Parking assistance	Front and back
Coloured windows	
Electric windows	
Electric mirrors	
Partition	
GPS navigation	
Color	Black
Heated mirrors	
Reversing camera	

### Drivetrain

Engine capacity	165 Kw (224 Hp)
Fuel type	diesel
Euro	5
Distribution type	Timing belt
Gearbox kind	Automatic
Power steering	
ABS	
ASR	

### Superstructure

Build kind	Medium length - Standard roof
Inner box length	157 cm
Inner box width	143 cm
Inner box height	128 cm
Load bed height	51 cm
Roof-rack	standard
Back doors	taillift

### Chairs

Number of seats	5
Seat cover	leather

### Remarks

Remarks	DUBBEL CABINE V6 3.0 LTR VOLLL
---------	--------------------------------

### Tyres/Wheels

Sparewheel

### Contact information




info@kleyn.com  
Tel: +31 183 668 444

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN VANS

**KLEYN** GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

## Inspection report

### Chassis

Dashboard display codes

Electrical

### Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

### Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

### Superstructure

Internal condition

External condition

### Tyres/Wheels

Tyres

## Tires and axles



1  
Tire size: 205/65R16,0  
coil spring suspension  
Disc brakes



2  
Tire size: 205/65R16,0  
air suspension  
Disc brakes

### Contact information



info@kleyn.com

Tel: +31 183 668 444

### Legenda for inspection report

Very good state  
 Good state  
 Reasonable state  
 Moderate state  
 Does not meet requirements