

VOLKSWAGEN CADDY



Itemno 309292
Kind Van
Specification Closed Van
Matriculation year 2014 / 08
Mileage 189,774 km

Chassisnumber
WV1ZZZ2KZFX011364

Technical condition

Remarks

(A15)



Price € 7900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	748 kg
Own weight	1,411 kg
Gross vehicle weight	2,159 kg
Unbraked towing capacity	700 kg
Braked towing capacity, center axle	1,400 kg
Wheelbase	268 cm
Aluminium rims	✓
Suspension type	spring suspension

Cabin

Cabin type	single cabin
Cruise control	✓
Airconditioning	✓
Number of airbags	1
Rear wiper	✓
Parking assistance	Back
Electric windows	✓
Electric mirrors	✓
Partition	✓
GPS navigation	✓
Color	white

Drivetrain

Engine capacity	55 Kw (75 Hp)
Fuel type	diesel
Euro	5
Distribution type	Timing belt
Gearbox kind	Manual
Number of Gears	5
Power steering	✓
ABS	✓
ASR	✓

Superstructure

Inner box length	170 cm
Inner box width	145 cm
Inner box height	121 cm
Load bed height	60 cm
Netto height	111 cm
Roof-rack	None
Sidedoors	1
Back doors	Double door

Chairs

Number of seats	2
Seat cover	cloth

Tyres/Wheels

Sparewheel	✓
------------	---

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



1
Tire size: 225/40R18,0
coil spring suspension
Disc brakes



2
Tire size: 225/40R18,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements