

RENAULT MASTER 2.3 L2H2 Airco Navi!



Itemno 309295
Kind Van
Specification Closed Van
Matriculation year 2020 / 06
Mileage 134,287 km

Chassisnumber
VF1MA000765633488

Technical condition

Remarks
L2H2 Airco Navi Trekhaak 3-Zits Cruise
(A15)

Price €18800

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	1,351 kg
Own weight	1,949 kg
Gross vehicle weight	3,300 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,500 kg
Towing bracket	
Wheelbase	368 cm
Suspension type	spring suspension

Cabin

Cabin type	single cabin
Cruise control	
Airconditioning	
Number of airbags	2
Parking assistance	Front and back
Electric windows	
Electric mirrors	
Partition	
GPS navigation	
Color	white
maintenance Guide	
Heated mirrors	

Drivetrain

Engine capacity	100 Kw (136 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing chain
Gearbox kind	Manual
Number of Gears	6
Power steering	
ABS	
ASR	

Superstructure

Inner box length	305 cm
Inner box width	177 cm
Inner box height	200 cm
Load bed height	58 cm
Netto height	184 cm
Rear step	
Roof-rack	None
Back doors	Double door

Chairs

Number of seats	3
Seat cover	cloth

Remarks

Remarks	L2H2 Airco Navi Trekhaak 3-Zits Cruise 135Pk Euro6!
---------	--

Tyres/Wheels

Sparewheel	
Spare tire profile	8 mm

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 225/65R16,0
coil spring suspension
Disc brakes



Tire size: 225/65R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements