

## MERCEDES-BENZ SPRINTER 313 L2H2!



Itemno 309364  
Kind Van  
Specification Closed Van  
Matriculation year 2010 / 06  
Mileage 193,073 km

**Chassisnumber**  
WDB9066331S477219

Technical condition

### Remarks

L2H2!

( A15 )

**Price €5900**

# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

## Equipment

### Chassis

Number of axles 2  
Configuration 4x2  
Own weight 2,335 kg  
Gross vehicle weight 3,500 kg  
Towing bracket  
Wheelbase 367 cm  
Suspension type spring suspension

### Cabin

Cabin type single cabin  
Number of airbags 1  
Parking assistance None  
Electric windows  
Electric mirrors  
Partition  
Color Green

### Drivetrain

Engine capacity 95 Kw (129 Hp)  
Fuel type diesel  
Distribution type Timing chain  
Gearbox kind Manual  
Number of Gears 6  
Power steering  
ABS  
ASR

### Superstructure

Inner box length 330 cm  
Inner box width 178 cm  
Inner box height 191 cm  
Load bed height 68 cm  
Netto height 181 cm  
Roof-rack None  
Sidedoors 1  
Back doors Double door

### Chairs

Number of seats 3  
Seat cover cloth

### Remarks

Remarks L2H2!

### Tyres/Wheels

Sparewheel

### Contact information



info@kleyn.com


Tel: +31 183 668 444

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN VANS

**KLEYN** GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

## Inspection report

### Chassis

Dashboard display codes

Electrical

### Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

### Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

### Superstructure

Internal condition

External condition

### Tyres/Wheels

Tyres

## Tires and axles



1

Tire size: 235/65R16,0  
spring suspension  
Disc brakes



2

Tire size: 235/65R16,0  
spring suspension  
Disc brakes

### Contact information



info@kleyn.com

Tel: +31 183 668 444

### Legenda for inspection report

Very good state  
 Good state  
 Reasonable state  
 Moderate state  
 Does not meet requirements