FORD TRANSIT 2.0 350 TDCI 130



Itemno Kind Specification Matriculation year Mileage Chassisnumber WF0DXXTTGDHP34632

309383 Van Open with sideboards 2017/06 139,188 km



Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles Configuration Loading Capacity Own weight Gross vehicle weight Unbraked towing capacity Braked towing capacity, center axle Towing bracket Wheelbase Suspension type

Cabin

Cabin type Cruise control Airconditioning Number of airbags Parking assistance Electric windows Electric mirrors **GPS** navigation Color maintenance Guide Heated mirrors Reversing camera

Drivetrain

Engine capacity Fuel type Euro Distribution type Gearbox kind Number of Gears Power steering ABS ASR

4x2 1,359 kg 2,141 kg 3,500 kg 750 kg 2,800 kg

2

350 cm spring suspension

single cabin

6 None

Green

96 Kw (130 Hp) diesel 6 Timing belt Manual 6

Superstructure

Inner box length Inner box width Inner box heigth Load bed heigth Roof-rack Back doors

Chairs

Number of seats Seat cover

Remarks Remarks

Tyres/Wheels Sparewheel

240 cm 214 cm 40 cm 86 cm None taillift

3 cloth

open laadbak, kist, airco, navi, trekhaak, camera

Contact information




info@kleyn.com Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



Inspection report

Chassis	
Dashboard display codes	
Electrical	
Cabin	
Internal	
External	
Steering column	
Suspension	
Chassis	
Brakes	
Drivetrain	
Engine, general	
Cooling system	
Fuel system	
Exhaust system	
Greasing system	
Gearbox	
Clutch	
Drivetrain	
Superstructure	
Internal condition	
External condition	

Tyres/Wheels

Tyres

Contact information



info@kleyn.com Tel: +31 183 668 444

Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Tires and axles



spring suspension Disc brakes

Legenda for inspection report	
	Very good state
	Good state
00000	Reasonable state
00000	Moderate state
00000	Does not meet requirements