

M.A.N. TGE 3.180 3.180



Itemno 309518
Kind Van
Specification Closed Van
Matriculation year 2021 / 04
Mileage 113,635 km

Chassisnumber
WMA03VUY7M9016141

Technical condition

Remarks
AC AUTOMAAT CRUISE EURO6
(A15)

Price € 28950

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Own weight 2,130 kg
Gross vehicle weight 3,500 kg
Towing bracket √
Wheelbase 367 cm
Suspension type spring suspension

Cabin

Cabin type single cabin
Cruise control √
Airconditioning √
Number of airbags 1
Parking assistance Front and back
Coloured windows √
Electric windows √
Electric mirrors √
Partition √
GPS navigation √
Color white
Heated mirrors √
Reversing camera √

Drivetrain

Engine capacity 130 Kw (177 Hp)
Fuel type diesel
Euro 6
Distribution type Timing belt
Gearbox kind Automatic
Power steering √
ABS √
ASR √

Superstructure

Build kind Medium length - High roof
Inner box length 326 cm
Inner box width 176 cm
Inner box height 198 cm
Load bed height 57 cm
Rear step √
Roof-rack None
Back doors Double door

Chairs

Number of seats 3
Seat cover leather

Remarks

Remarks AC AUTOMAAT CRUISE
EURO6

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



1
Tire size: 205/75R16,0
coil spring suspension
Disc brakes



2
Tire size: 205/75R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements