

MERCEDES-BENZ VITO 114



Itemno 309567
Kind Van
Specification Closed Van
Matriculation year 2017 / 12
Mileage 253,160 km

Chassisnumber
WDF44760313406341

Technical condition

Remarks
AC AUTOMAAT EURO6
(A15)



Price €14950

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	848 kg
Own weight	1,952 kg
Gross vehicle weight	2,800 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,500 kg
Towing bracket	
Wheelbase	320 cm
Aluminium rims	
Suspension type	coil spring suspension

Cabin

Cabin type	single cabin
Cruise control	
Airconditioning	
Number of airbags	2
Parking assistance	Front and back
Coloured windows	
Electric windows	
Electric mirrors	
Partition	
GPS navigation	
Color	Black
Heated mirrors	
Reversing camera	

Drivetrain

Engine capacity	100 Kw (136 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing belt
Gearbox kind	Automatic
Power steering	
ABS	
ASR	

Superstructure

Build kind	Medium length - Standard roof
Inner box length	240 cm
Inner box width	165 cm
Inner box height	133 cm
Load bed height	60 cm
Roof-rack	standard
Back doors	Double door

Chairs

Number of seats	3
Seat cover	cloth

Remarks

Remarks	AC AUTOMAAT EURO6
---------	-------------------

Tyres/Wheels

Sparewheel	
------------	--

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes ☐ ☐ ☐ ☐ ☐

Electrical ☐ ☐ ☐ ☐ ☐

Cabin

Internal ☐ ☐ ☐ ☐ ☐

External ☐ ☐ ☐ ☐ ☐

Steering column ☐ ☐ ☐ ☐ ☐

Suspension ☐ ☐ ☐ ☐ ☐

Chassis ☐ ☐ ☐ ☐ ☐

Brakes ☐ ☐ ☐ ☐ ☐

Drivetrain

Engine, general ☐ ☐ ☐ ☐ ☐

Cooling system ☐ ☐ ☐ ☐ ☐

Fuel system ☐ ☐ ☐ ☐ ☐

Exhaust system ☐ ☐ ☐ ☐ ☐

Greasing system ☐ ☐ ☐ ☐ ☐

Gearbox ☐ ☐ ☐ ☐ ☐

Clutch ☐ ☐ ☐ ☐ ☐

Drivetrain ☐ ☐ ☐ ☐ ☐

Superstructure

Internal condition ☐ ☐ ☐ ☐ ☐

External condition ☐ ☐ ☐ ☐ ☐

Tyres/Wheels

Tyres ☐ ☐ ☐ ☐ ☐

Tires and axles



Tire size: 225/55R17,0
coil spring suspension
Disc brakes



Tire size: 225/55R17,0
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

☐ ☐ ☐ ☐ ☐ Very good state
☐ ☐ ☐ ☐ ☐ Good state
☐ ☐ ☐ ☐ ☐ Reasonable state
☐ ☐ ☐ ☐ ☐ Moderate state
☐ ☐ ☐ ☐ ☐ Does not meet requirements