

## VOLKSWAGEN TRANSPORTER 2.0 TDI



Itemno 309800  
Kind Van  
Specification Closed Van  
Matriculation year 2016 / 05  
Mileage 155,406 km

**Chassisnumber**  
WV1ZZZ7HZGH052464

Technical condition

### Remarks

L2 AIRCO

( A15 )

**Price €13450**

# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

## Equipment

### Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	977 kg
Own weight	1,823 kg
Gross vehicle weight	2,800 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,200 kg
Towing bracket	
Wheelbase	340 cm
Suspension type	coil spring suspension

### Cabin

Cabin type	single cabin
Cruise control	
Airconditioning	
Number of airbags	2
Rear wiper	
Parking assistance	None
Coloured windows	
Electric windows	
Electric mirrors	
Partition	
GPS navigation	
Color	white
Heated mirrors	

### Drivetrain

Engine capacity	75 Kw (102 Hp)
Fuel type	diesel
Euro	5
Distribution type	Timing belt
Gearbox kind	Manual
Number of Gears	5
Power steering	
ABS	
ASR	

### Superstructure

Build kind	Medium length - Standard roof
Inner box length	276 cm
Inner box width	163 cm
Inner box height	137 cm
Load bed height	64 cm
Roof-rack	None
Back doors	Double door

### Chairs

Number of seats	2
Seat cover	cloth

### Remarks

Remarks	L2 AIRCO
---------	----------

### Tyres/Wheels

Sparewheel

### Contact information



info@kleyn.com


Tel: +31 183 668 444

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

## Inspection report

### Chassis

Dashboard display codes

Electrical

### Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

### Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

### Superstructure

Internal condition

External condition

### Tyres/Wheels

Tyres

## Tires and axles



1

Tire size: 215/65R16,0  
coil spring suspension  
Disc brakes



2

Tire size: 215/65R16,0  
coil spring suspension  
Disc brakes

### Contact information



info@kleyn.com

Tel: +31 183 668 444

### Legenda for inspection report

Very good state  
 Good state  
 Reasonable state  
 Moderate state  
 Does not meet requirements